

Inspection Photos

April 28th, 2025

Operator: Logos Operating LLC - 10679

Location ID: 307022

Inspection Document #: 714002117

La Plata County, CO

Township: SWSE 16 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

April 28, 2025
343° N



LOGOS OPERATING, LLC.
ESPINOSA #001A MV
FEL
API NO. 067-09595
990' FSL & 2403' FEL
SEC.16 T32N R06W N4PM
LA PLATA COUNTY, CO
LAT: 37.01572 LONG: 107.51075
EMERGENCY CONTACT # 1-866-598-6220
CO 91

Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: Espinosa 1A
Location ID: 307022



Photo 2. Musk thistle observed on location, approximately 10 individuals observed.

Inspection Photos
Location Name: Espinosa 1A
Location ID: 307022

April 28, 2025
310° NW



April 28, 2025
318° NW



Photo 3. View of location cut slope which remains with bare soils and weedy debris.