

Inspection Photos
Location Name: FOSS/6-35
Location #: 306706



Photo #1

Foss 6-35 (123-25138) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 20 yds.



Photo #2

Foss 6-32, 6-31 Wellsite(s)

Wellsite(s) entrance

Formerly served:

Foss 6-33, 6.34, 6-35

Plugged & Abandoned | PA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FOSS/6-35
Location #: 306706



Photo #3
Foss 6-32, 6-31 Battery site
Inactive | Shut-down
Equipment documented: Fac. ID 487904
Formerly served:
Foss 6-33, 6.34, 6-35
Plugged & Abandoned | PA



Photo #4
Foss 6-32, 6-31 Battery site
Inactive | Shut-down
Battery entrance

