

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31D-20-691 Pad**  
**Location ID: 335481**



**Location Overview: Location is within High  
Priority/Density/Black Bear Habitat areas.**

**Section/Township/Range: 20 6S91W**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31D-20-691 Pad**  
**Location ID: 335481**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31D-20-691 Pad**  
**Location ID: 335481**



**Photo # 7958 Failure to minimize erosion & the transport of sediment off location/insufficient BMP's (W/NW edge of location)**



**Photo # 7959 Failure to minimize erosion & the transport of sediment off location/insufficient BMP's (W/NW edge of location)**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31D-20-691 Pad**  
**Location ID: 335481**



**Photo # 7960 Failure to minimize erosion & the transport of sediment off location/insufficient BMP's (W/NW edge of location)**



**Photo # 7961 Failure to minimize erosion & the transport of sediment off location/insufficient BMP's (W/NW edge of location)**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31D-20-691 Pad**  
**Location ID: 335481**



**Photo # 7962 Failure to minimize erosion & the transport of sediment off location/insufficient BMP's (W/NW edge of location)**