

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31D-20-691 Pad

Location ID: 335481



Photo # 7948 From entrance to location



Photo # 7949 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31D-20-691 Pad

Location ID: 335481



Photo # 7950 Improperly marked deadman



Photo # 7951 Same improperly marked deadman

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31D-20-691 Pad

Location ID: 335481



Photo # 7952 Same improperly marked deadman from a different angle



Photo # 7953 Wellhead sign lacks the public road used to access the site/not in compliance with CECMC rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31D-20-691 Pad

Location ID: 335481



Photo # 7954 Wellhead sign lacks the public road used to access the site/not in compliance with CECMC rules

Photo # 7955 Wellhead sign lacks the public road used to access the site/not in compliance with CECMC rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31D-20-691 Pad

Location ID: 335481



Photo # 7956 Wellhead sign lacks the public road used to access the site/not in compliance with CECMC rules

Photo # 7957 Wellhead sign lacks the public road used to access the site/not in compliance with CECMC rules