

Inspection Photos  
Location Name: RANDALL 22-2  
Location ID: 320134



Photo #1 Tank (weeds)




Photo #2 Separator & Meter (weeds)

**Inspection Photos**  
**Location Name: RANDALL 22-2**  
**Location ID: 320134**



**Photo #3 Unused tank weeds**



**Photo #4 No access to well head**