

Inspection Photos  
Location Name: State 16-7-60-1H  
Location ID: 432352



Photo 1 – Pumping Unit



Photo 2 – Wildlife Netting in disrepair

Inspection Photos  
Location Name: State 16-7-60-1H  
Location ID: 432352





Photo 3 – Wellhead



Photo 4 – Contact Number is Previous' Operators

**Inspection Photos**  
**Location Name: State 16-7-60-1H**  
**Location ID: 432352**



**Photo 5 – ECD and Flare**



**Photo 6 – Heater Treater, Gas Meter and VRU**

Inspection Photos  
Location Name: State 16-7-60-1H  
Location ID: 432352



Photo 7 – Tank Battery



Photo 8 – Tank Battery Sign – Contact Number is Previous' Operarators

Inspection Photos  
Location Name: State 16-7-60-1H  
Location ID: 432352



Photo 9 – Tank Battery

Photo 10 – Tank Battery

Inspection Photos  
Location Name: State 16-7-60-1H  
Location ID: 432352



**Photo 11 – Sign at Entrance - Contact Number is Previous' Operators**