

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

04/15/2025

Document Number:

404165206

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: <u>88370</u>	Contact Person: <u>Todd Pivonka</u>
Company Name: <u>TIMKA RESOURCES LTD</u>	Phone: <u>(970) 590-5617</u>
Address: <u>2077 BAYFRONT DR</u>	Fax: <u>()</u>
City: <u>WINDSOR</u> State: <u>CO</u> Zip: <u>80550</u>	Email: <u>timkaresources@hotmail.com</u>

Identification Information

API Number: 05 - <u> </u> - <u> </u>	ECMC Facility ID: <u>159174</u>	Initial Form 19 or 27 Document number: <u> </u>
Facility Name: <u>THEURER #1-B</u>	Facility Number: <u> </u>	Facility Type: <u>UIC DISPOSAL</u>
Location QtrQtr: <u>NESW</u>	Section: <u>28</u>	Township: <u>3N</u>
	County: <u>WASHINGTON</u>	Range: <u>52W</u>
		Meridian: <u>6</u>
		Field Name: <u>PINTO</u>
Federal, Indian or State Lease Number: <u> </u>		

Information Submitted By:

Company Name: <u>CGRS, Inc</u>	Agent Name: <u>Lauren Glazer</u>	Title: <u>Consultant</u>
Phone Number: <u>800-288-2657</u>	Email: <u>lglazier@cgrs.com</u>	

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: <u>159174</u>	Facility Name: <u>THEURER #1-B</u>	Facility Type: <u>UIC DISPOSAL</u>
Location: QtrQtr: <u>NESW</u>	Sec: <u>28</u>	Twp: <u>3N</u>
	County Name: <u>WASHINGTON</u>	Range: <u>52W</u>
	Latitude: <u>40.197190</u>	Meridian: <u>6</u>
		Longitude: <u>-103.201390</u>

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: <u>125981</u>	Document Name: <u>EDD</u>	File Name: <u>2025_0305-Theurer 1B_CGRS EDD AA18472.xlsx</u>
SampleType: <u> </u>	Matrix: <u> </u>	
Facility ID: <u>159174</u>	Sample ID: <u>666455</u>	Sample Name: <u>Theurer 1-B</u>
		Sample Date: <u>03/05/2025</u>
Collection Point: <u>Tank</u>	Matrix: <u>WATER</u>	Pre Post: <u>806.a-UIC initial Analysis</u>
Project Number: <u>29368</u>	Remediation Number: <u> </u>	Complaint Number: <u> </u>
		NOAV Number: <u> </u>
Inspection Number: <u> </u>	Spill Number: <u> </u>	Laboratory: <u>Elevation Diagnostics</u>
		Lab Sample ID: <u>AA19472</u>

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
159174	404165229	2025_0305_Theurer 1B_AA18472.pdf	Analytical Laboratory Report	PDF

Sample ECMC Well Related:

Sample ID	API Num	Well Name & Num	Sample Reason
666455	121-10444	THEURER 1-B	

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	05/02/2025

Total: 1 comment(s)