

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT RMV 16-35 Pad

Location ID: 323890



Photo # 7532 From entrance to location




Photo # 7533 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT RMV 16-35 Pad

Location ID: 323890



Photo # 7534 Location




Photo # 7535 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT RMV 16-35 Pad

Location ID: 323890



Photo # 7536 Location



Photo # 7537 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT RMV 16-35 Pad

Location ID: 323890



Photo # 7538 Debris in the interim area