

Inspection Photos

April 14th, 2025

Operator: American Helium - 10841

Location ID: 316866

Inspection Document #: 714002140

San Miguel County, CO

Township: SWNE 7 44N 14W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Apr 14, 2025
34° NE



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: HC Fed 7-14-44-14
Location ID: 316866



Photo 2. Unused solar panel and fittings equipment observed on location.

Apr 14, 2025
188° S



Apr 14, 2025
169° S

