



<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
API No. 05- 103 - 9607		LEASE NAME: Exxon #1	
LOCATION: SWSW, 18, 35, 95 W		OPERATOR: Strachan Expl.	
DATE: 12-12-95		INSPECTOR: Adkins	
Insp. Type: PR	Insp. Status: PR	PA: Y N	Pass/Fail: (P) F Viol.: Y (N) NOV: Y (N)

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210)	Good	
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904)	open steel vault, blowdown pit	
<b>Fences</b> (Rule 604.C.(3), 1003.A)	none	
<b>Tank Battery Equipment</b> (Rule 604)	Small Compressor, meter run, separator, Dehy unit, vault, med hand tank, 200 BBL tank	
<b>Fire Walls/Berms/Dikes</b> (Rule 604)	not adequate	
<b>General Housekeeping</b> (Rule 603.G)	good!	
<b>Spills (Oil/Water)</b> (Rule 908)	none	
<b>Bradenhead</b> (Rule 207)	100 psi, producing fuel gas from Bradenhead	
<b>Drilling Well/Workover</b> (Rule 315)		
<b>Surface Rehabilitation</b> (Rule 317)	oil stained soil on plastic liner in bermed area	
<b>Miscellaneous</b>	TP = 80 I producing fuel gas from backside (flange top) Bradenhead 100#	

**CORRECTIVE ACTION REQUIRED:**

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.