

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 15-35 Pad

Location ID: 323901



Photo # 8641 From entrance to location




Photo # 8642 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 15-35 Pad

Location ID: 323901



Photo # 8643 Location



Photo # 8644 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 15-35 Pad

Location ID: 323901



Photo # 8645 Location



Photo # 8646 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 15-35 Pad

Location ID: 323901




Photo # 8647 Location




Photo # 8648 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 15-35 Pad

Location ID: 323901




Photo # 8649 Location



Photo # 8650 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 15-35 Pad

Location ID: 323901



Photo # 8651 Location



Photo # 8652 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 15-35 Pad

Location ID: 323901



Photo # 8653 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 8654 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 15-35 Pad

Location ID: 323901



Photo # 8655 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 8656 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 15-35 Pad

Location ID: 323901



Photo # 8657 There are a total of three 300 bbl tanks in battery on location, 2 condensate & 1 produced water. FORM 2A document # 400130017 submitted by operator lists 2 condensate tanks & 0 water tanks/not in compliance with CECMC rules

