

Inspection Photos

Loc: 307341

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 5/6/2025

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing west at the wellsite.



Inspection Photos



Photo 2. Facing toward the pumpjack and produced water pit which has adequate freeboard.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307341 | Date: 5/6/2025

Inspection Photos



Photo 3. Sign is posted on the meter shed.

