

# Final Reclamation Inspection

April 17, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 327672

Inspection Document #: 718800174

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: WARD #30-1J  
Location ID: 327672



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that site does not meet Rule 1004 final reclamation standards as gravel remains on location and weedy annual vegetation, including russian thistle (*Salsola tragus*) was observed throughout location.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: WARD #30-1J  
Location ID: 327672



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: WARD #30-1J  
Location ID: 327672



**Photo 5.** Photo taken from the access road, facing West. Photo illustrates that gravel remains along the access road and russian thistle is present across the site.



**Photo 6.** Photo taken from the access road, facing West, towards the well site. See comments under Photo 5.



Inspection Photos  
Location Name: WARD #30-1J  
Location ID: 327672



**Photo 7.** Photo taken of the well site. Photo illustrates gravel that remains on location.



**Photo 8.** Photo taken from the reference area, north of the well location, facing North.

Inspection Photos  
Location Name: WARD #30-1J  
Location ID: 327672



**Photo 9.** Photo of the tank battery location, facing South. Photo illustrates the tank battery location is contained within a land use change.



**Photo 10.** Photo of the tank battery location, facing Southwest. See comments under Photo 9.