

Final Reclamation Inspection

April 17, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 329226

Inspection Document #: 718800178

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GLOVER #30-7J
Location ID: 329226



Photo 1. Photo taken from the well location, facing North. Photo illustrates that Operator has performed final reclamation activities with evidence of drill row seeding, however vegetation does not meet Rule 1004 final reclamation standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: GLOVER #30-7J
Location ID: 329226



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: GLOVER #30-7J
Location ID: 329226



Photo 5. Photo taken from the access road, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill rows, but vegetation establishment does not meet final reclamation standards.



Photo 6. Photo taken from the access road, facing South, towards the location. See comments under Photo 5.



Inspection Photos
Location Name: GLOVER #30-7J
Location ID: 329226



Photo 7. Photo taken of the well site. Photo illustrates weedy annual growth including kochia (*Kochia scoparia*) and Russian thistle (*Salsola tragus*).



Photo 8. Photo taken from the reference area, north of the well location, facing West. Photo illustrates sandy soil with perennial grass and shrub vegetation.

