

Final Reclamation Inspection

April 23, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 331616

Inspection Document #: 718800223

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FOSTER #9-4A
Location ID: 331616



Photo 1. Photo taken from the well location, facing North. Photo illustrates that the site does not meet Rule 1004 standards as there is weedy growth and vegetation establishment does not reflect reference area conditions.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: FOSTER #9-4A
Location ID: 331616



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: FOSTER #9-4A
Location ID: 331616



Photo 5. Photo taken of the access road, at the entrance to the location, facing Northeast. Photo illustrates that vegetation establishment does not meet Rule 1004 reclamation standards.



Photo 6. Photo taken of the access road, facing South. See comments under Photo 5.

Inspection Photos
Location Name: FOSTER #9-4A
Location ID: 331616



Photo 7. Photo taken of the reference area, southwest of the location, facing East. Photo illustrates perennial grass vegetation.