

Final Reclamation Inspection

April 23, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 318115

Inspection Document #: 718800227

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MEL ANDERSON GAS UNIT #1
Location ID: 318115



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to final reclamation standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: MEL ANDERSON GAS UNIT #1
Location ID: 318115



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos

Location Name: MEL ANDERSON GAS UNIT #1

Location ID: 318115



Photo 5. Photo taken of the access road, facing southwest away from the well location. Photo illustrates that final reclamation activities have taken place, with evidence of drill rows, but vegetation establishment does not meet final reclamation standards.



Photo 6. Photo taken of the well location. Photo illustrates that some perennial vegetation has established at the site, but establishment does not meet Rule 1004 standards.



Inspection Photos
Location Name: MEL ANDERSON GAS UNIT #1
Location ID: 318115



Photo 7. Photo taken of the reference area, south of the location, facing East. Photo illustrates area is dominated by perennial grass vegetation.

