

# Final Reclamation Inspection

April 23, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 336169

Inspection Document #: 718800237

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HSR ALTER  
FEDERAL-61N66W/5NESE  
Location ID: 336169



**Photo 1.** Photo taken from the multi-well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill rows, but vegetation establishment does not meet final reclamation standards.



**Photo 2.** Photo taken from the multi-well location, facing East. See comments under Photo 1.





Inspection Photos  
Location Name: HSR ALTER  
FEDERAL-61N66W/5NESE  
Location ID: 336169



**Photo 3.** Photo taken from the multi-well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the multi-well location, facing West. See comments under Photo 1.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 718800237



Inspection Photos  
Location Name: HSR ALTER  
FEDERAL-61N66W/5NESE  
Location ID: 336169



**Photo 5.** Photo taken of the tank battery location, facing North. Photo illustrates that there is evidence of drill rows from seeding activities, but vegetation has not established to Rule 1004 reclamation standards.



**Photo 6.** Photo taken of the tank battery location, facing South. See comments under Photo 5.



Inspection Photos  
Location Name: HSR ALTER  
FEDERAL-61N66W/5NESE  
Location ID: 336169



**Photo 7.** Photo taken of the access road, facing North. Photo illustrates that vegetation has reestablished partially on this portion of the access road, while the northern portion of the access road remains unreclaimed.



**Photo 8.** Photo taken of the access road, facing North. Photo illustrates that this portion of the access road has not been reclaimed.



Inspection Photos  
Location Name: HSR ALTER  
FEDERAL-61N66W/5NESE  
Location ID: 336169



**Photo 9.** Photo taken of the reference area, east of the location, facing South. Photo illustrates perennial grass vegetation.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 718800237