

Final Reclamation Inspection

April 30, 2025

Operator: SUNDANCE ENERGY INC - 10340

Location ID: 318136

Inspection Document #: 718800257

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CAVEY #21-24
Location ID: 318136



Photo 1. Google Earth aerial imagery from October 7, 2012. Photo illustrates the well location during active operations



Inspection Photos
Location Name: CAVEY #21-24
Location ID: 318136




Photo 2. Google Earth aerial imagery from September 4, 2023. Photo illustrates the well location after plugging operations. The site has undergone a land use change to a residential area.



Inspection Photos
Location Name: CAVEY #21-24
Location ID: 318136



Photo 3. Photo taken of the well location, facing Southeast. Photo illustrates that the site is contained within a land use change to a residential area.

