

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203

Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404193443

Receive Date:

Report taken by:

## Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

## OPERATOR INFORMATION

Name of Operator: NOBLE ENERGY INC	Operator No: 100322	Phone Numbers
Address: 1099 18TH STREET SUITE 1500		Phone: (970) 313-5582
City: DENVER	State: CO	Zip: 80202
Contact Person: Jason Davidson	Email: jason.davidson@chevron.com	Mobile: ( )

## PROJECT, PURPOSE &amp; SITE INFORMATION

## PROJECT INFORMATION

Remediation Project #: 35770 Initial Form 27 Document #: 403746638

## PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☐ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☒ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☐ Other: \_\_\_\_\_

## SITE INFORMATION

No Multiple Facilities

Facility Type: WELL	Facility ID: _____	API #: 123-24538	County Name: WELD
Facility Name: TORRES-USX AB 35-9	Latitude: 40.528050	Longitude: -104.510100	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: NESE	Sec: 35	Twp: 7N	Range: 64W
Meridian: 6	Sensitive Area? Yes		

## SITE CONDITIONS

General soil type - USCS Classifications SW Most Sensitive Adjacent Land Use Grassland

Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

#### Other Potential Receptors within 1/4 mile

Well Within Pronghorn Winter Concentration Area HPH  
Well Within Mule Deer Severe Winter Range HPH  
Residential 0.18mi NE  
Farm Structure 0.15mi E, 0.15/0.17/0.18/2/0.21/0.22/0.24mi NE  
Apparent Pond 0.14mi E, 0.2mi SW

## SITE INVESTIGATION PLAN

### TYPE OF WASTE:

☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste

☒ Produced Water

☐ Workover Fluids

☒ Oil

☐ Tank Bottoms

☒ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

### DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	NA	Lab analysis if encountered
Yes	SOILS	Refer to ECMC Document No 404080914	Lab analysis and field screening

### INITIAL ACTION SUMMARY

Description of initial action or emergency response measures taken to abate, investigate, and/or remediate impacts associated with E&P Waste.

Pursuant to ECMC Rule 911 a site investigation was conducted pertaining to the TORRES USX AB35-09 wellhead cut and cap and flowline removal. The wellhead was cut and capped per ECMC rules. Additionally, soil samples were field screened at the N-E-S-W sides of the wellhead. Approximately 1211' of flowline was removed. Soil sampling and screening samples were taken along the flowline at any points of material change and/or hammer unions, and directional changes. Laboratory analytical samples were analyzed for full ECMC Table 915-1 contaminants of concern.

The confirmation soil samples collected during wellhead cut and cap activities were determined to be outside of the required temperature preservation range when delivered to the laboratory. Re-sampling will be conducted at a later date and will be provided in a subsequent Supplemental Form 27 upon completion.

### PROPOSED SAMPLING PLAN

#### Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

A grab soil sample was collected at the base of the excavation or the area showing the highest degree of impact during field screening activities at the wellhead excavation. Additionally, soil samples were field screened at the N-E-S-W sides of the wellhead. Soil samples were collected along the flowline at any points of material change and/or hammer unions, and directional changes. Soil samples were analyzed by a certified laboratory for the full extent of Table 915-1, including but not limited to: TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons) organic compounds in soil per ECMC Table 915-1, and EC, SAR, pH, metals, and boron. All samples collected will be analyzed by a certified laboratory using approved ECMC laboratory analysis methods.

#### Proposed Groundwater Sampling

☒ Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

If groundwater is encountered during the site investigation a grab groundwater sample will be collected and analyzed for all organic and inorganic compounds per ECMC Table 915-1.

#### Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

The confirmation soil samples collected during wellhead cut and cap activities were determined to be outside of the required temperature preservation range when delivered to the laboratory. Re-sampling will be conducted at a later date and will be provided in a subsequent Supplemental Form 27 upon completion.

## SITE INVESTIGATION REPORT

## **SAMPLE SUMMARY**

### **Soil**

Number of soil samples collected 5  
Number of soil samples exceeding 915-1 2  
Was the areal and vertical extent of soil contamination delineated? No  
Approximate areal extent (square feet) 200

### **Groundwater**

Number of groundwater samples collected 0  
Was extent of groundwater contaminated delineated? Yes  
Depth to groundwater (below ground surface, in feet)           
Number of groundwater monitoring wells installed           
Number of groundwater samples exceeding 915-1         

### **Surface Water**

0 Number of surface water samples collected  
         Number of surface water samples exceeding 915-1  
If surface water is impacted, other agency notification may be required.

### **NA / ND**

ND Highest concentration of TPH (mg/kg)           
         Highest concentration of SAR           
         BTEX > 915-1 No  
         Vertical Extent > 915-1 (in feet) 4  
NA Highest concentration of Benzene (µg/l)           
NA Highest concentration of Toluene (µg/l)           
NA Highest concentration of Ethylbenzene (µg/l)           
NA Highest concentration of Xylene (µg/l)           
NA Highest concentration of Methane (mg/l)         

## **OTHER INVESTIGATION INFORMATION**

☐ Were impacts to adjacent property or offsite impacts identified?

☒ Were background samples collected as part of this site investigation?

Twenty (20) background samples were collected under the nearby Garcia USX AB35-10D flowline project (REM# 37319) and analyzed for metals in soil per ECMC Table 915-1, pH, SAR, EC, and boron. Background soil samples were collected from depths ranging between 0-1 feet and 8 feet below ground surface (ft bgs). The maximum concentration for pH was observed to be 8.68. The maximum background concentrations with a 1.25x multiplier for arsenic, barium, and cadmium were observed to be 11.98 mg/kg, 360 mg/kg, and 0.470 mg/kg, respectively. All arsenic, barium, and cadmium concentrations observed during decommissioning were below background levels.

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)          Volume of liquid waste (barrels)         

☒ Is further site investigation required?

Based on decommissioning analytical results, a supplemental site investigation (SSI) will be completed to vertically and horizontally delineate the pH exceedances observed at sample locations FL01R-S@4' and FL01-07@4'. Soil samples will be submitted for analysis of the full ECMC Table 915-1 analytical suite. A proposed SSI map is attached to this Form 27. The SSI will be completed in accordance with the proposed implementation schedule, and the results of the SSI will be submitted on a subsequent Form 27.

The confirmation soil samples collected during wellhead cut and cap activities were determined to be outside of the required temperature preservation range when delivered to the laboratory. Re-sampling will be conducted at a later date and will be provided in a subsequent Supplemental Form 27 upon completion.

## **REMEDIAL ACTION PLAN**

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

## **SOURCE REMOVAL SUMMARY**

Describe how source is to be removed.

No impacted material caused by oil and gas operations was identified at this time.

## **REMEDIATION SUMMARY**

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Analytical results received for samples collected during flowline decommissioning activities indicated that organic compound concentrations were in compliance with the applicable ECMC regulatory standards in all soil sample locations. Based on the results for the remaining analytes, a supplemental site investigation (SSI) will be completed to vertically and horizontally delineate the pH exceedances observed at sample locations FL01R-S@4' and FL01-07@4'. A proposed SSI map is attached to this Form 27.

## Soil Remediation Summary

☐ In Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Air sparge / Soil vapor extraction  
\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

☐ Ex Situ

\_\_\_\_\_ Excavate and offsite disposal  
\_\_\_\_\_ If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_  
\_\_\_\_\_ Name of Licensed Disposal Facility or ECMC Facility ID # \_\_\_\_\_  
\_\_\_\_\_ Excavate and onsite remediation  
\_\_\_\_\_ Land Treatment  
\_\_\_\_\_ Bioremediation (or enhanced bioremediation)  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Other \_\_\_\_\_

## Groundwater Remediation Summary

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Air sparge / Soil vapor extraction  
\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

## GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was not encountered during decommissioning activities.

## REMEDIATION PROGRESS UPDATE

### PERIODIC REPORTING

#### Approved Reporting Schedule:

☒ Quarterly☐ Semi-Annually☐ Annually☐ Other

#### ☐ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

#### Report Type:

☐ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☒ Other Second Quarter 2025 Timeline Update

### Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policies MWZZ316714 and MWZX316724) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 50000

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

## REMEDIATION COMPLETION REPORT

### REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

☐ Compliant with Rule 913.h.(1).

☐ Compliant with Rule 913.h.(2).

☐ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards?

Does the previous reply indicate consideration of background concentrations?

Does Groundwater meet Table 915-1 standards? \_\_\_\_\_

Is additional groundwater monitoring to be conducted? \_\_\_\_\_

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

## RECLAMATION PLAN

### **RECLAMATION PLANNING**

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? Yes \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☒ Interim ☐ Final

Did the Surface Owner provide the seed mix? \_\_\_\_\_

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? \_\_\_\_\_

### **SITE RECLAMATION DATES**

Proposed date of commencement of Reclamation. 07/23/2024

Proposed date of completion of Reclamation. 11/08/2026

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### **PRIOR DATES**

Date of Surface Owner notification/consultation, if required. 04/04/2024

Actual Spill or Release date, or date of discovery. \_\_\_\_\_

### **SITE INVESTIGATION DATES**

Date of Initial Actions described in Site Investigation Plan (start date). 07/23/2024

Proposed site investigation commencement. 05/08/2025

Proposed completion of site investigation. 11/08/2025

### **REMEDIAL ACTION DATES**

Proposed start date of Remediation. 11/08/2025

Proposed date of completion of Remediation. 05/08/2026

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☒ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

The implementation schedule has been changed due to necessity for supplemental site investigation (SSI) activities at the site. The SSI will be scheduled following the approval of ECMC Document Number 404080914.

## OPERATOR COMMENT

This Form 27 is being submitted as a second quarter 2025 timeline update for TORRES USX AB 35-09 wellhead and flowline location.

A summary of flowline decommissioning activities was included on ECMC Document Number 404080914, which is in-process and pending approval at the time of this submittal.

Based on the results of flowline decommissioning activities, a supplemental site investigation (SSI) will be completed to vertically and horizontally delineate the pH exceedances observed at sample locations FL01R-S@4' and FL01-07@4'. Soil samples will be submitted for analysis of the full ECMC Table 915-1 suite. A proposed SSI map is attached to this Form 27. The SSI will be completed in accordance with the proposed implementation schedule, and the results of the SSI will be submitted on a subsequent Form 27.

The confirmation soil samples collected during wellhead cut and cap activities were determined to be outside of the required temperature preservation range when delivered to the laboratory. Re-sampling will be conducted at a later date and will be provided in a subsequent Supplemental Form 27 upon completion.

Pursuant to Rule 913.e, Supplemental Form 27s will be submitted on a quarterly schedule to provide updates and progress of the remediation until closure criteria is met.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Jimmy Webster

Title: Environmental Consultant

Submit Date: \_\_\_\_\_

Email: tas-chevron-2@tasman-geo.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

Remediation Project Number: 35770

## COA Type

## Description

0 COA	

## ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

## Att Doc Num

## Name

404195544	SITE INVESTIGATION PLAN
-----------	-------------------------

Total Attach: 1 Files

## General Comments

## User Group

## Comment

## Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)