

Inspection Photos

05/6/2025

Operator: GUNNISON ENERGY LLC - 10515

Location ID: 324485

Inspection Doc: 718100509

Gunnison County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324485



Photo 1: Photos 1-3 taken from the south end of the working pad surface. Photos provide an overview of the Location from west, northwest, northeast, southeast to southwest. Location and access road are subject to 1004 Final reclamation requirements including, but not limited to removal of gravel, compaction alleviation, recontouring/regrading, replacement of topsoil and revegetation activities by 7/9/2025.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324485



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324485



Photo 3: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324485



Photo 4: Photo taken from the Topsoil stockpile on the northwest end of the Location. BMPs to stabilize soils remain missing or insufficient; soils are bare and at risk to wind and water erosion.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324485



Photo 5: Continued from photo 5. Photo example showing unstabilized soils continue to erode, with sediment covering established vegetation at the stockpile



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324485



Photo 6: Photo taken from the west end of the Location, facing southwest. Photo shows surface equipment (pipe) has not been removed from the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources