

WELL NAME: DOLLY VARDEN 41-20, API #: 071-06181, INSP. # 716300948



PHOTO 1: WELL SIGN



PHOTO 2: LOCATION.



PHOTO 3: WELLHEAD AND EQUIPMENT.





PHOTO 4: TANK BATTERY.





PHOTO 5: TBG/CSG ANNULUS IS PLUMBED TO CRUDE OIL TANK BATTERY AND VALVES APPEAR TO BE OPEN.



WGS84
±24ft

38.38572, -105.12740

ft
±17ft

5278

°M
±11

S188



Colorado Oil & Gas Conservation commission
© 09-May-25 10:25:00

PHOTO 6: TBG/CSG ANNULUS. GAS CAN BE SEEN IN THE ATTACHED FLIRR VIDEO ON HIGH RES.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



PHOTO 7: THERE IS AN AREA OF IMPACTED SOIL ON BACKSIDE OF TANK BATTERY NEAR 2" VALVE. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D CA DATE 5/21/2025.