

Inspection Photos
Location Name: Razor 25B PAD
Location ID: 436427



Photo 1 – ECDs



Photo 2 – Tank Battery

Inspection Photos
Location Name: Razor 25B PAD
Location ID: 436427



Photo 3 – Tank Battery Sign

Photo 4 – LACT

Inspection Photos
Location Name: Razor 25B PAD
Location ID: 436427



Photo 5 – Heater Treaters



Photo 6 – Heater Treaters

Inspection Photos
Location Name: Razor 25B PAD
Location ID: 436427



Photo 7 – Open Candlestick Flare



Photo 8 – Open Candlestick Flare

Inspection Photos
Location Name: Razor 25B PAD
Location ID: 436427



Photo 9 – Compressor



Photo 10 – Compressor

Inspection Photos
Location Name: Razor 25B PAD
Location ID: 436427



Photo 11 – Signage missing on Compressor Drain Vault




Photo 12 – Wellheads

Inspection Photos
Location Name: Razor 25B PAD
Location ID: 436427




Photo 13 – 25B-2449 Wellhead




Photo 14 – Gas Lift Injection Meter House

Inspection Photos
Location Name: Razor 25B PAD
Location ID: 436427



Photo 15 – Wellheads



Photo 16 – 25B-2551 Wellhead

Inspection Photos
Location Name: Razor 25B PAD
Location ID: 436427



Photo 17 – Signs at Entrance