

Inspection Photos
Location Name: Razor 33M-2804
Location ID: 436724



Photo 1 – South end of Berm is compromised

Photo 2 – East Center of Berm is compromised

Inspection Photos
Location Name: Razor 33M-2804
Location ID: 436724



Photo 3 – Tank Battery



Photo 4 – Pumping Unit

Inspection Photos
Location Name: Razor 33M-2804
Location ID: 436724



Photo 5 – Wellhead