

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
404125612  
Receive Date:  
03/12/2025

Report taken by:  
Chris Sanchez

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECOM is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>NOBLE ENERGY INC</u>	Operator No: <u>100322</u>	<b>Phone Numbers</b>
Address: <u>1099 18TH STREET SUITE 1500</u>		
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Jason Davidson</u>	Email: <u>jason.davidson@chevron.com</u>	Phone: <u>(970) 313-5582</u>
		Mobile: <u>( )</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 26813 Initial Form 27 Document #: 403293139

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: \_\_\_\_\_

SITE INFORMATION

No  Multiple Facilities

Facility Type: <u>WELL</u>	Facility ID: _____	API #: <u>123-25434</u>	County Name: <u>WELD</u>
Facility Name: <u>SPIKE STATE CC 30-20</u>	Latitude: <u>40.283074</u>	Longitude: <u>-104.484568</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>NESW</u>	Sec: <u>30</u>	Twp: <u>4N</u>	Range: <u>63W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SW Most Sensitive Adjacent Land Use Rangeland  
 Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? No  
 Is groundwater less than 20 feet below ground surface? No

**Other Potential Receptors within 1/4 mile**

Well Within Pronghorn Winter Concentration Area HPH  
No other potential receptors are located within 1/4 mile of the Site.  
Above distances are approximations.

**SITE INVESTIGATION PLAN**

**TYPE OF WASTE:**

- E&P Waste       Other E&P Waste       Non-E&P Waste
- Produced Water       Workover Fluids
- Oil       Tank Bottoms
- Condensate       Pigging Waste
- Drilling Fluids       Rig Wash
- Drill Cuttings       Spent Filters
- Pit Bottoms
- Other (as described by EPA)

**DESCRIPTION OF IMPACT**

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	NA	Lab analysis if encountered
No	SOILS	NA	Lab analysis

**INITIAL ACTION SUMMARY**

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Pursuant to ECMC Rule 911 a site investigation will be conducted pertaining to the SPIKE STATE CC30-20 wellhead cut and cap and flowline removal. Approximately 862' of flowline was removed. The wellhead will be cut and capped per ECMC rules. Additionally, soil samples were collected at any points of material change and/or hammer unions, directional changes, as well as at the bell holes on either side of a waterway, AS APPLICABLE to abandonment type.

**PROPOSED SAMPLING PLAN**

**Proposed Soil Sampling**

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

A grab soil sample was collected at the base of the excavation or the area showing the highest degree of impact during field screening activities at the wellhead excavation. Additionally, soil samples were collected along the flowline at any points of material change and/or hammer unions, directional changes, as well as at the bell holes on either side of a waterway, AS APPLICABLE to abandonment type. A grab confirmation soil sample was collected at the wellhead excavation. Soil samples were analyzed by a certified laboratory for TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons) organic compounds in soil per ECMC Table 915-1, and EC, SAR, pH, and boron. All samples collected were analyzed by a certified laboratory using approved ECMC laboratory analysis methods.

**Proposed Groundwater Sampling**

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

Change to past tense and update sample numbers if groundwater was encountered and sampled. If wrong, update.

**Proposed Surface Water Sampling**

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

[Empty box for surface water sampling details]

**Additional Investigative Actions**

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

Visual inspection along the flowline and at the wellhead and separator areas occurred during abandonment activities. Field personnel field screened all disturbed areas using visual and olfactory senses to determine if laboratory confirmation sampling was required. The applicable ECMC Closure Checklists were utilized and filled out during the abandonment process. A photolog was attached on a previous form document number 403904627.

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 2

Number of soil samples exceeding 915-1 1

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 50

### NA / ND

-- Highest concentration of TPH (mg/kg) 1

-- Highest concentration of SAR 0.888

BTEX > 915-1 No

Vertical Extent > 915-1 (in feet) 4

### Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? Yes

Depth to groundwater (below ground surface, in feet) \_\_\_\_\_

Number of groundwater monitoring wells installed \_\_\_\_\_

Number of groundwater samples exceeding 915-1 \_\_\_\_\_

\_\_\_\_\_ Highest concentration of Benzene (µg/l) \_\_\_\_\_

\_\_\_\_\_ Highest concentration of Toluene (µg/l) \_\_\_\_\_

\_\_\_\_\_ Highest concentration of Ethylbenzene (µg/l) \_\_\_\_\_

\_\_\_\_\_ Highest concentration of Xylene (µg/l) \_\_\_\_\_

\_\_\_\_\_ Highest concentration of Methane (mg/l) \_\_\_\_\_

### Surface Water

0 Number of surface water samples collected

0 Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) \_\_\_\_\_

Volume of liquid waste (barrels) \_\_\_\_\_

Is further site investigation required?

Per the COA issued by the ECMC via document number 403904627, the previously field screened locations FL01 (3'), FL02 (3'), FL03 (4'), and the wellhead flowline riser tie in will be resampled. The soil samples collected adjacent to the flowline will be submitted for laboratory analysis for Full Table 915-1 Contaminants of Concern. Additionally, background soil samples will be collected to characterize native soil conditions at the site. Background soil samples will be analyzed by a certified laboratory for analysis of metals per ECMC Table 915-1 and soil suitability parameters including pH, EC, SAR, and boron. The proposed flowline and background sample locations are included in the attached Site Maps included on document number 404022752. The proposed sampling will be completed in accordance with the proposed implementation schedule, and the results of the additional investigative actions will be submitted on a subsequent Form 27.

## REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

### SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Impacted soil was not discovered during removal of the flowlines. Based on site investigation activities and laboratory analytical results of confirmation soil samples collected from the flowline risers, along the flowlines, and from the separator flowline riser, removal of soil is not needed. The material excavated during flowline removal activities was used as backfill for the excavations.

### REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Based on site investigation activities and laboratory analytical results for confirmation soil samples collected from the flowline risers, along the flowlines, and from the separator flowline riser, a remediation plan is not needed.

### **Soil Remediation Summary**

**In Situ**

**Ex Situ**

- \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Air sparge / Soil vapor extraction
- \_\_\_\_\_ Natural Attenuation
- \_\_\_\_\_ Other \_\_\_\_\_

- \_\_\_\_\_ Excavate and offsite disposal
- \_\_\_\_\_ If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_
- \_\_\_\_\_ Name of Licensed Disposal Facility or ECMC Facility ID # \_\_\_\_\_
- \_\_\_\_\_ Excavate and onsite remediation
- \_\_\_\_\_ Land Treatment
- \_\_\_\_\_ Bioremediation (or enhanced bioremediation)
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Other \_\_\_\_\_

### **Groundwater Remediation Summary**

- \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Air sparge / Soil vapor extraction
- \_\_\_\_\_ Natural Attenuation
- \_\_\_\_\_ Other \_\_\_\_\_

### **GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was not encountered.

# REMEDIATION PROGRESS UPDATE

## PERIODIC REPORTING

### Approved Reporting Schedule:

Quarterly    Semi-Annually    Annually    Other

### Request Alternative Reporting Schedule:

Semi-Annually    Annually    Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type:    Groundwater Monitoring    Land Treatment Progress Report    O&M Report

Other Supplemental Form 27: Timeline update

## Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policy MWZZ 316714) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 50000

## WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_

E&P waste (solid) description \_\_\_\_\_

ECMC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-ECMC Disposal Facility: \_\_\_\_\_

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_

E&P waste (liquid) description \_\_\_\_\_

ECMC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-ECMC Disposal Facility: \_\_\_\_\_

# REMEDIATION COMPLETION REPORT

## REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? No

Does the previous reply indicate consideration of background concentrations? \_\_\_\_\_

Does Groundwater meet Table 915-1 standards? Yes

Is additional groundwater monitoring to be conducted? \_\_\_\_\_

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? Yes

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim  Final

Did the Surface Owner provide the seed mix? \_\_\_\_\_

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? \_\_\_\_\_

### SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 04/02/2026

Proposed date of completion of Reclamation. 04/02/2029

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. 12/29/2022

Actual Spill or Release date, or date of discovery. \_\_\_\_\_

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 03/30/2023

Proposed site investigation commencement. 02/11/2024

Proposed completion of site investigation. 07/31/2025

### REMEDIAL ACTION DATES

Proposed start date of Remediation. \_\_\_\_\_

Proposed date of completion of Remediation. \_\_\_\_\_

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

The implementation schedule has been changed due to the need to resample soil sample locations FL01 (3'), FL02 (3'), FL03 (4'), and the wellhead flowline riser tie in at the Spike State CC 30-20. The proposed resampling will be completed following the approval of this form.

**OPERATOR COMMENT**

This form serves to comply with the Rule 913.e. reporting schedule. The review status of the previously proposed workplan (Doc. # 404022752) is "In Process" on Web Forms. Pending ECMC EPS form review/approval, the Operator will complete the additional site investigation and remediation as outlined on Doc. # 404022752 and this F27. Supplemental Form 27s will be prepared and submitted on a quarterly schedule to provide updates and progress of the remediation until closure criteria has been achieved.

Decommissioning activities at the Spike State CC30-20 revealed a different flowline path other than depicted on the initial approved soil sample location map.

Per the COA issued by the ECMC via document number 403904627, the operator will go back and resample the flowline at any points of material change and/or hammer unions, directional changes, as well as at the bell holes on either side of a waterway as applicable to the actual flowline path, and additionally collect background samples. Please refer to the site investigation as outlined in this proposed Site Investigation Report workplan and the attached proposed confirmation and background soil sample location map (Figures 2 & 3) for sample locations included on document number 404022752. Noble will request an NFA be granted if the analyzed samples comply with the Table 915-1 concentration standard. Background soil samples will be collected to characterize native soil conditions at the site.

Remediation of Separator Tie-in Spill consolidated to Rem. # 26863. Approved on Doc. # 403809267.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Ethan Black

Title: Consultant

Submit Date: 03/12/2025

Email: ethanb@fremontenv.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Chris Sanchez

Date: 05/09/2025

Remediation Project Number: 26813

**COA Type****Description**

	ECMC has processed this form as an update; no analytical was attached thus approval of this form does not imply any agreement with comments on completion of site investigation. All ongoing/unaddressed comments/COAs from previous Forms remain applicable.
1 COA	

**ATTACHMENT LIST**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num****Name**

404125612	INVESTIGATION/REMEDATION WORKPLAN (SUPPLEMENTAL)
404197986	FORM 27-SUPPLEMENTAL-SUBMITTED

Total Attach: 2 Files

**General Comments****User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)