

Inspection Photos

05/6/2025

Operator: GUNNISON ENERGY LLC - 10515

Location ID: 490082

Inspection Doc: 718100518

Gunnison County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location ID: 490082



Photo 1: Photos 1-2 taken from central areas of the Location. Photos provide an overview of the Location from North, East, South and West.

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 490082



Photo 2: Photo shows tank on Location. Photo left shows containment berm has been damaged. Photo right also shows various trash/debris (wood, rubbish, etc...).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 490082



Photo 3: Unused hose equipment. Photo right also shows open pipe riser.

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 490082



Photo 4: Photo example showing noxious weed (Common Mullein, Musk thistle) establishment throughout the Location



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources