

Final Reclamation Inspection

April 10, 2025

Operator: NOBLE ENERGY INC - #100322

Location ID: 305414

Inspection Document #: 697505892

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PETERSON 1-35
Location ID: 305414



Photo 1. Photo taken from the northern well location access road, facing South. Photo illustrates the access road meets Rule 1004 vegetative standards.



Photo 2. Photo taken from the southern well location access road, facing Southeast. See comments under Photo 1.

Note- perimeter fence remains around the location.

Inspection Photos
Location Name: PETERSON 1-35
Location ID: 305414



Photo 3. Photo taken from the central location, facing East. Photo illustrates the location meets Rule 1004 vegetative standards.



Photo 4. Photo taken from the central location, facing North. See comments under Photo 3.



Inspection Photos
Location Name: PETERSON 1-35
Location ID: 305414



Photo 5. Photo taken from the central location, facing West.
See comments under Photo 3.



Photo 6. Photo taken from the central location, facing South.
See comments under Photo 3.

Inspection Photos
Location Name: PETERSON 1-35
Location ID: 305414



Photo 7. Operator supplied photo illustrates that the perimeter fence has been removed after my inspection.