

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Kaufman (Pad #7)/23A-24-692

Location ID: 413453

Date: 5/8/2025



Location Overview – Photo #08584



Location – Photo #08585

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Kaufman (Pad #7)/23A-24-692

Location ID: 413453

Date: 5/8/2025



Location – Photo #08588



Location – Photo #08589

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Kaufman (Pad #7)/23A-24-692

Location ID: 413453

Date: 5/8/2025



Location – Photo #08591



Location – Photo #08590

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Kaufman (Pad #7)/23A-24-692

Location ID: 413453

Date: 5/8/2025



Illegible Wellhead Sign – Photo #08586

Illegible Wellhead Sign – Photo #08587

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Kaufman (Pad #7)/23A-24-692

Location ID: 413453

Date: 5/8/2025



Stored Supplies/Wildlife Entry Hazard – Photo #08592



Stored Supplies/Wildlife Entry Hazard – Photo #08593