

# Inspection Photos

Loc: 481042

Operator: BNL (ENTERPRISE) INC

Inspection Date: 5/9/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northwest toward the beginning of the access road. The road has not been reclaimed. The sign has fallen over.



## Inspection Photos



**Photo 2.** Facing west along the access road which is not establishing vegetation.



## Inspection Photos



**Photo 3.** Facing west toward the location. Sign is posted at the location.




**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:481042 | Date: 5/9/2025

## Inspection Photos



**Photo 4.** Facing west toward the location. There are two areas of remediation with open excavations.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:481042 | Date: 5/9/2025

## Inspection Photos



**Photo 5.** Facing north at the excavation around the wellhead. Remediation remains in process.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:481042 | Date: 5/9/2025

## Inspection Photos



**Photo 6.** Center of the location facing east..



## Inspection Photos



**Photo 7.** Center of the location facing west.



## Inspection Photos



**Photo 8.** View of vegetation cover throughout the location consists of mostly weedy annuals such as Warty spurge, Little barley, Russian thistle, Sunflower among other.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:481042 | Date: 5/9/2025

## Inspection Photos



**Photo 9.** Facing west toward the southwest corner where remediation and excavated material remains.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:481042 | Date: 5/9/2025

## Inspection Photos



**Photo 10.** Facing toward the excavation at the southwest corner.



## Inspection Photos



**Photo 12.** Facing south toward the surrounding undisturbed area which consists of native perennial vegetation.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:481042 | Date: 5/9/2025