

# Final Reclamation and Stormwater Inspection

May 7, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 320314

Well Name: N COLORADO 44-13 #9

Inspection Document #: 718600563

Adams County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: N COLORADO 44-13 #9  
Location ID: 320314



**Photo 1.** Picture taken at the entrance of the well location. Culvert remains in place.



**Photo 2.** Looking west down the access road. Road remains in place without vegetation establishment.





Inspection Photos  
Location Name: N COLORADO 44-13 #9  
Location ID: 320314



**Photo 3.** Large patches of undesirable weed Kochia are present near the wellhead.



**Photo 4.** Looking west from wellbore. Some desirable vegetation is beginning to establish around the wellbore. Vegetation coverage is lower than the surrounding area and undesirable weeds such as kochia are present.





Inspection Photos  
Location Name: N COLORADO 44-13 #9  
Location ID: 320314



**Photo 5.** Looking south from wellbore. See photo 4 comments.



**Photo 6.** Looking east from wellbore. See photo 4 comments.





Inspection Photos  
Location Name: N COLORADO 44-13 #9  
Location ID: 320314



**Photo 7.** Looking north from wellbore. See photo 4 comments.



**Photo 8.** Reference vegetation to the north of well location.





Inspection Photos  
Location Name: N COLORADO 44-13 #9  
Location ID: 320314



**Photo 9.** Looking east down the tank battery access road from the tank battery. Road appears to be in use by the landowner to access their garage and driveway.



**Photo 10.** Looking north down tank battery access road. Road appears to have been expanded by the landowner.





Inspection Photos  
Location Name: N COLORADO 44-13 #9  
Location ID: 320314



**Photo 11.** Looking west across the tank battery location from the east side. Large patches of bare earth or undesirable weed Kochia are present. Some desirable vegetation has established on the location.



**Photo 12.** Photo taken on the west side of the tank battery looking west. Illustrating a bare/ weedy patch.





Inspection Photos  
Location Name: N COLORADO 44-13 #9  
Location ID: 320314



**Photo 13.** Looking down the south side of the tank battery location.