

# Final Reclamation and Stormwater Inspection

May 7, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 320311

Well Name: N. COLORADO BLVD #24-13-8

Inspection Document #: 718600565

Adams County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: N. COLORADO BLVD #24-13-8  
Location ID: 320311



**Photo 1.** Looking across the wellbore. It appears this location underwent a land use change to residential housing and was recontoured. No oil and gas equipment remains.



**Photo 2.** It appears the landowner is watering a large area including the well location to grow vegetation.



Inspection Photos  
Location Name: N. COLORADO BLVD #24-13-8  
Location ID: 320311



**Photo 3.** Looking south across the tank battery location. Desirable vegetation is present and weeds appear to be controlled at the time of inspection. Vegetation coverage is lower than the reference area particularly on the north side of the location.



**Photo 4.** Looking west across the south side of the tank battery location. Illustrating lower vegetation establishment and bare areas.

Inspection Photos  
Location Name: N. COLORADO BLVD #24-13-8  
Location ID: 320311



**Photo 5.** Looking north from the south side of the tank battery. See photo 3 comments.



**Photo 6.** Picture taken at the north side of the location. A small bunker/shooting range is constructed on the tank battery.



Inspection Photos  
Location Name: N. COLORADO BLVD #24-13-8  
Location ID: 320311



**Photo 7.** Excavation shooting range in the center of the tank battery. Vegetative coverage is also visible.



**Photo 8.** Looking south at the north side of the tank battery. Bare soil is present.



Inspection Photos  
Location Name: N. COLORADO BLVD #24-13-8  
Location ID: 320311



**Photo 9.** Reference vegetation to the north of the tank battery.