

**Operator: BONANZA CREEK ENERGY OPERATING
COMPANY**

Location Name: North Platte T-23 Pad

Loc ID: 470863

Inspection: 707603673



Exhibit A

CA: Unnecessary equipment at Location site. See Northeast side of Location site. Unnecessary equipment includes: Frac tank w/ spill pad. Refer to Rule 606 for guidance. Remove unnecessary equipment from Location site. Comply with Rule 606. Corrective Action date: 03/21/2025. (30 days). See photo(s) #1, 2, 3. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.

CA Resolution: Operator has removed the equipment in order to comply with Rule 606.