

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404194053

Date Received:

05/09/2025

Spill report taken by:

Metz, Collin

Spill/Release Point ID:

490144

SPILL/RELEASE REPORT (INITIAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to ECMC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

OPERATOR INFORMATION

| | | |
|--|---------------------------|---|
| Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u> | Operator No: <u>47120</u> | Phone Numbers |
| Address: <u>P O BOX 173779</u> | | Phone: <u>(970) 515-0055</u> |
| City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-3779</u> | | Mobile: <u>()</u> |
| Contact Person: <u>Jaron Bartoszek</u> | | Email: <u>DJRemediation_Forms@oxy.com</u> |

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 404194053

Initial Report Date: 05/07/2025 Date of Discovery: 05/07/2025 Spill Type: Historical Release

Spill/Release Point Location:

QTRQTR SWSW SEC 31 TWP 4N RNG 67W MERIDIAN 6

Latitude: 40.263057 Longitude: -104.940451

Municipality (if within municipal boundaries): _____ County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

Check this box if this spill/release is related to a loss of integrity of a flowline, pipeline, crude oil transfer line, or produced water transfer line.

Reference Location:

Facility Type: TANK BATTERY Facility/Location ID No 445565
 Spill/Release Point Name: Frank 23, 14, Russell 19, 13-31 Well API No. (Only if the reference facility is well) 05- -
 No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

| | |
|---|--|
| Estimated Oil Spill Volume(bbl): <u>Unknown</u> | Estimated Condensate Spill Volume(bbl): <u>Unknown</u> |
| Estimated Flow Back Fluid Spill Volume(bbl): <u>0</u> | Estimated Produced Water Spill Volume(bbl): <u>Unknown</u> |
| Estimated Other E&P Waste Spill Volume(bbl): <u>0</u> | Estimated Drilling Fluid Spill Volume(bbl): <u>0</u> |

Specify: _____

Has the subject Spill/Release been controlled at the time of reporting? Yes

Land Use:

Current Land Use: CROP LAND Other(Specify): _____
 Weather Condition: 68°, Sunny
 Surface Owner: FEE Other(Specify): _____

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

While conducting tank battery removal activities at the Frank 23,14,Russell 19, 13-31 Facility, historically impacted soil was discovered above tank battery liner at aboveground storage tanks (AST) AST01 and AST02. The volume of the release is unknown. Assessment activities are ongoing. The historically impacted soil will be removed and disposed of and confirmation soil samples will be collected in compliance with ECMC Table 915-1. Additionally, a waste characterization sample of the impacted material has been collected and submitted for analysis of full ECMC Table 915-1 constituents. Analytical results will be provided in a subsequent report. The topographic Site Location Map showing the geographic setting of the release is provided as Figure 1.

List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):

OTHER NOTIFICATIONS

| Date | Agency/Party | Contact | Phone | Response |
|----------|---------------|---------------|-------|--------------------|
| 5/7/2025 | Surface Owner | Surface Owner | --- | Notified via email |
| 5/7/2025 | Weld County | Weld County | --- | Notified via email |

REPORT CRITERIA

Rule 912.b.(1) Report to the Director (select all criteria that apply):

No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: _____ Public Water System: _____
 Residence or Occupied Structure: _____ Livestock: _____
 Wildlife: _____ Publicly-Maintained Road: _____

No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery _____ (HH:MM)
 Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 _____
 Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? _____
 Enter the Document Number of the Initial Accident Report, Form 22 _____
 Was there damage during excavation? _____
 Was CO 811 notified prior to excavation? _____

No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): _____

No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:

- The presence of free product or hydrocarbon sheen Surface Water
- The presence of free product or hydrocarbon sheen on Groundwater
- The presence of contaminated soil in contact with Groundwater
- The presence of contaminated soil in contact with Surface water

| | |
|-----|--|
| Yes | Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight from the subsurface. |
| No | Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property. <input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way |
| No | Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps. |
| No | Rule 912.b.(1).J: A Release that results in natural gas in Groundwater. |

OPERATOR COMMENTS:

| |
|--|
| |
|--|

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Jaron Bartoszek

Title: Environmental Advisor Date: 05/09/2025 Email: DJRemediation_Forms@oxy.com

| <u>COA Type</u> | <u>Description</u> |
|-----------------|---|
| 1 COA | Per Rule 912.b.(4), the Operator shall make a supplemental report on Form 19 not more than 10 calendar days after the spill/release is discovered that includes: A. A topographic map showing the governmental section and location of the spill or an aerial photograph showing the location of the spill B. All pertinent information about the spill/release known to the Operator that has not been reported previously including photo documentation showing the source of the Spill or Release, the impacted area, and initial cleanup activity C. Information relating to the initial mitigation, site investigation, and remediation measures conducted by the Operator D. Global Positioning System data that meets the requirements of Rule 216 if latitude and longitude data provided pursuant to Rule 912.b.(2).A did not meet the requirements of Rule 216. |

ATTACHMENT LIST

| <u>Att Doc Num</u> | <u>Name</u> |
|--------------------|---------------------|
| 404194053 | FORM 19 SUBMITTED |
| 404197480 | CORRESPONDENCE |
| 404197494 | TOPOGRAPHIC MAP |
| 404197623 | PHOTO DOCUMENTATION |

Total Attach: 4 Files

General Comments

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|-------------------|----------------|---------------------|
| | | Stamp Upon Approval |

Total: 0 comment(s)