

# Final Reclamation and Stormwater Inspection

May 13, 2025

Operator: BISON IV OPERATING LLC- #10670

Location ID: 421908

Inspection Document #: 697505902

Weld County, CO

Chris Binschus  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Wagner 11-65 11-1H  
Location ID: 421908



**Photo 1.** Photo taken from the southeastern location, facing North. Photo illustrates desirable species were patchy with bare ground throughout the location.



**Photo 2.** Photo taken from the southeastern location, facing West. See comments under Photo 1.

# Inspection Photos

Location Name: Wagner 11-65 11-1H

Location ID: 421908



**Photo 3.** Photo taken from the central location, facing North.  
See comments under Photo 1.



**Photo 4.** Photo taken from the central location, facing West.  
See comments under Photo 1.



Inspection Photos  
Location Name: Wagner 11-65 11-1H  
Location ID: 421908



**Photo 5.** Photo taken from the northern access road, facing South. See comments under Photo 1.

Note- the southern access road had the best observed establishment.

