

Final Reclamation and Stormwater Inspection

May 13, 2025

Operator: BISON IV OPERATING LLC- #10670

Location ID: 422671

Inspection Document #: 697505904

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Wagner #11-65 9-1H
Location ID: 422671



Photo 1. Photo taken from the northeastern location, facing North. Photo illustrates desirable species were patchy with bare ground throughout the location.



Photo 2. Photo taken from the northeastern location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: Wagner #11-65 9-1H
Location ID: 422671



Photo 3. Photo taken from the southwestern location, facing North. See comments under Photo 1.



Photo 4. Photo taken from the southwestern location, facing East. See comments under Photo 1.