

Inspection Photos
Location Name: Brophy WDW 42-13 4N46W
API Number: 125-11177



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Brophy WDW 42-13 4N46W
API Number: 125-11177



3. Pressure gauge installed on tubing valve.



4. Pressure gauge installed on casing valve.