

Inspection Photos
Location Name: Gilbert 01-03
API Number: 125-10827



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Gilbert 01-03
API Number: 125-10827



3. Pressure gauge installed on tubing valve.



4. Pressure gauge installed on casing valve.

Inspection Photos
Location Name: Gilbert 01-03
API Number: 125-10827



5. View of Well House.



6. Well location overview.