

Operator: HIGHPOINT OPERATING CORPORATION

Location Name: Will 6-62-15_22 NENW

Loc ID: 438766

Inspection: 718700201



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F



Exhibit F



Exhibit G



Exhibit H

CA: Hydrocarbon staining observed at equipment and throughout location. Refer to attached inspection photos. Conduct maintenance on equipment, cleanup stained material and review self-inspection processes per Rule 1002.f.(2).D.

CA Resolution: Operator has addressed the issues in order to comply with Rule 1002.f.(2).D.