

# Inspection Photos

ID: 321894

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 5/13/2025

County: CHEYENNE



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast toward the abk battery facility..



## Inspection Photos



**Photo 2.** There is an active remediation occurring at the battery. It appears there are still impact shown at red arrow that should be cleaned up better..



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321894 | Date: 5/13/2025

## Inspection Photos



**Photo 3.** There is a bucket of oil shown at red arrow. This needs to be cover and contained.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321894 | Date: 5/13/2025

## Inspection Photos



**Photo 4.** Facing toward the impact material stored onsite. A secondary containment berm needs to be installed around the entire pile.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:321894 | Date: 5/13/2025

## Inspection Photos



**Photo 5.** Facing southwest at the location.



## Inspection Photos



**Photo 6.** The interim area at the southeast side consists of entirely undesirable weeds (Kochia).



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321894 | Date: 5/13/2025

## Inspection Photos



**Photo 7.** West side of the location facing north. There is another pile of impacted material stored at red arrow.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321894 | Date: 5/13/2025

## Inspection Photos



**Photo 8.** This active tank has no secondary containment.

