

Inspection Photos

API: 017-07483

Operator: **HELENA RESOURCES INC**

Inspection Date: 5/13/2025

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 2. Facing toward the wellhead pumpjack.



Inspection Photos



Photo 3. Facing toward the tank battery which does not have sufficiently sized secondary containment to contain a spill.



Inspection Photos



Photo 4. Facing northeast overlooking the location.



Inspection Photos



Photo 5. Facing north at the west side of the location. The topsoil pile is not revegetated or stabilized.



Inspection Photos



Photo 6. Facing toward the northeast side of the location. There are areas that are bare of vegetation that need to be seeded.

