

Inspection Photos

API: 063-06328

Operator: **UNIT PETROLEUM COMPANY**

Inspection Date: 5/13/2025

County: KIT CARSON



Inspection Photos



Photo 1. Facing north toward the access road which was not regraded, contoured, or reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 2. Facing north toward the location. This area at location entrance is bare of vegetation. There are perimeter fence posts and wire that have not been removed.



Inspection Photos



Photo 3. Center of the location facing north. Perennial vegetation is progressing throughout the location.



Inspection Photos



Photo 4. Center of the location facing west. Perennial vegetation is progressing throughout the location.



Inspection Photos



Photo 5. Center of the location facing south. Perennial vegetation is progressing throughout the location.



Inspection Photos



Photo 6. Center of the location facing east. Perennial vegetation is progressing throughout the location.

