

Inspection Photos
Location Name: Bashor PC GQ 17-04
Location ID: 417833



Photo 1 – Sign at Entrance – Previous Operator’s Number still present



Photo 2 – Tank Battery

Inspection Photos
Location Name: Bashor PC GQ 17-04
Location ID: 417833



Photo 3 – NFPA Label missing on Water Tank



Photo 4 – Signage does not reflect current Operator

Inspection Photos
Location Name: Bashor PC GQ 17-04
Location ID: 417833



Photo 5 – Tank Battery



Photo 6 – Heater Treater

Inspection Photos
Location Name: Bashor PC GQ 17-04
Location ID: 417833



Photo 7 – Heater Treater, Gas Meter and ECD



Photo 8 – Well Sign

Inspection Photos
Location Name: Bashor PC GQ 17-04
Location ID: 417833



Photo 9 – Pumping Unit



Photo 10 – Wellhead

Inspection Photos
Location Name: Bashor PC GQ 17-04
Location ID: 417833



Photo 11 – Well Sign