

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC DODGE 8-12 (L8E) Pad

Location #: 324004



Photo # 472 From entrance to location




Photo # 473 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC DODGE 8-12 (L8E) Pad

Location #: 324004



Photo # 474 Location



Photo # 475 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC DODGE 8-12 (L8E) Pad

Location #: 324004



Photo # 476 Location



Photo # 477 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC DODGE 8-12 (L8E) Pad

Location #: 324004



Photo # 478 Emergency contact # on wellhead sign incorrect/not in compliance with CECMC rules



Photo # 479 Emergency contact # on wellhead sign incorrect/not in compliance with CECMC rules

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC DODGE 8-12 (L8E) Pad

Location #: 324004



Photo # 480 Weeds in secondary containment



Photo # 481 Weeds in secondary containment