

# Inspection Photos

API: 017-06678

Operator: **DECLAR OIL & GAS INC**

Inspection Date: 5/13/2025

County: CHEYENNE



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos




**Photo 1.** Drone aerial photo facing north along the access road and toward the location. There are areas of the access road that have not established vegetation shown at red arrow.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos



**Photo 2.** Drone aerial photo facing north downward toward the location. The location still remains fenced and most of the area is bare of vegetation inside the fenced area. .




**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06678 | Date: 5/13/2025

## Inspection Photos



**Photo 3.** Drone aerial photo facing south. This bare soil area is approximately 250x250 feet. It appears soils are impacted preventing vegetation establishment.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06678 | Date: 5/13/2025


## Inspection Photos



**Photo 4.** West side of the location facing east down toward the location. It appears soils are impacted preventing vegetation establishment.



## Inspection Photos



**Photo 5.** Facing northeast toward the surrounding reference area which consists of a uniform perennial vegetation cover.

