

## Inspection Photos

Location Name: State North Platte/O-26 Pad

Location #: 434745



Photo #1

State North Platte/O-26 Pad

**CA: Unnecessary Equipment**

*Frac tank w/ spill pad*

*Drone photo*

*Top: North (N)*

*prior photo*



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

State North Platte O-26 Pad Location ID #434745 Photos  
January 29, 2025

## Inspection Photos

Location Name: State North Platte/O-26 Pad

Location #: 434745



**Photo #2**

**State North Platte/O-26 Pad**

**CA: Unnecessary Equipment**

*Frac tank w/ spill pad*

*prior photo*



**Photo #3**

**State North Platte/O-26 Pad**

**CA: Unnecessary Equipment**

*Frac tank w/ spill pad*

*prior photo*



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

State North Platte O-26 Pad Location ID #434745 Photos  
January 29, 2025



## Inspection Photos

Location Name: State North Platte/O-26 Pad

Location #: 434745



**Photo #4**

**State North Platte/O-26 Pad**

*Drone photo*

*Top: North (N)*

*prior photo*



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

State North Platte O-26 Pad Location ID #434745 Photos  
January 29, 2025

## Inspection Photos

Location Name: State North Platte/O-26 Pad

Location #: 434745



January 29, 2025 at 12:43 PM

+40.3633, -104.3984

233° SW

Weld County

Energy & Carbon Management Commission

### Photo #5

State North Platte/O-26 Pad

*Location signage*

*prior photo*



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

State North Platte O-26 Pad Location ID #434745 Photos  
January 29, 2025



## Inspection Photos

Location Name: State North Platte/O-26 Pad

Location #: 434745



Photo #6

State North Platte/O-26 Pad

**CA: Unnecessary Equipment**

*Frac tank w/ spill pad*

**CA: Unnecessary Equipment remains on site**

**Follow-up inspection: FAIL**




Photo #7

State North Platte/O-26 Pad

**CA: Unnecessary Equipment**

*Frac tank w/ spill pad*

**CA: Unnecessary Equipment remains on site**

**Follow-up inspection: FAIL**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

State North Platte O-26 Pad Location ID #434745 Photos  
May 09, 2025