



Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#1 Photo at entry to  
location

May 16, 2025 11:35:03 AM  
40.574265606701374N 106.38338964432478W  
Unnamed Road  
Coalmont  
Jackson County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



40.5739437835291N 106.3825794495W  
May 16, 2025 11:36

582 Logan  
Jackson  
Co

Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#2 Containment  
area that holds pumps.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#3 Wellhead. Two  
wells on pad

May 16, 2025 11:38:02 AM  
40.573795130476356N 106.38232598081231W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#4 Wellhead. Two  
wells on pad

May 16, 2025 11:38:08 AM  
40.573750413022935N 106.38232916593552W  
Walden  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#5 two cellars to the south of SWD wells , in ECMC database the wells are listed as SO (suspended operations)

May 16, 2025 11:38:20 AM  
40.573679795488715N 106.38231818564236W  
Walden  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#6 4 wells 2 SWD  
wells to the north and 2  
SO wells to the south.

May 16, 2025 11:38:31 AM  
40.57363654486835N 106.38226470910013W  
Walden  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



40.573579631745815N 106.3817080669

May 16, 2025 11:39

Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#7 Northwest  
corner of Pintail Tank  
Battery.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources




Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#8 Northwest corner of Pintail Tank Battery. Looking east. It was reported by Fulcrum Field staff that the water in the secondary contaminants was from recent storms, it was stated that all spilled fluid was removed after the spill.

May 16, 2025 11:39:25 AM  
40.57357414159924N, 106.38169264420867W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#9 photo taken on  
west side of Battery  
looking east.

May 16, 2025 11:39:42 AM  
40.57351664174348N 106.38168158009648W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#10 photo taken on  
west side of Battery  
looking east.

May 16, 2025 11:40:02 AM  
40.57347242720425N 106.38168853707612W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#11 photo taken on  
west side of Battery  
looking east.

May 16, 2025 11:40:27 AM  
40.57342800311744N 106.38168945908546W  
Walden  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#12 South side of  
Tank Battery. Some  
debris on electrical, from  
birds?

May 16, 2025 11:41:22 AM  
40.573402270674706N, 106.38132384046912W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



May 16, 2025 11:42:03 AM  
40.57342297397554N 106.38095595873892W  
Walden  
Colorado

Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#13 equipment on  
east side of pad. line  
heater and free water  
knockout (?)



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



May 16, 2025 11:42:34 AM  
40.57344070170075N 106.38121906667948W  
Walden  
Colorado

Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#14 Photo taken from east side of TB looking south west.  
NOTE: Material at bottom right of photo. It is believed that this is insulation from the tanks. It is believed that birds are attempting to tunnel into the spray foam insulation on the tanks and the insulation is becoming airborne and collecting in the containment.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#15 Photo taken on  
east side of tank battery.  
Some observed foam  
from tank insulation.

May 16, 2025 11:42:45 AM  
40.57344539556652N 106.38121613301337W  
Walden  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#16 Photo taken from east side of TB looking west. Note: inside donut a bird was observed nesting, prevent nesting wildlife in equipment.

May 16, 2025 11:43:14 AM  
40.57350553572178N 106.38121169060469W  
Walden  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#17 Photo taken from east side of TB looking west. Note:foam and hydrocarbon staining.

May 16, 2025 11:43:41 AM  
40.573526322841644N 106.38121604919434W  
Walden  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Pintail Tank**  
**Battery Spill**  
**Location ID: 454414**  
**Inspection Date: 05/16/2025**

Photo#18 Photo taken  
from east side of TB  
looking west. Note: foam  
on water.

May 16, 2025 11:44:14 AM  
40.573601592332125N 106.38121143914759W  
Walden  
Colorado



**COLORADO**  
**Energy & Carbon Management**  
**Commission**  
Department of Natural Resources



Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#19 east side of  
tank battery.  
Note:hydrocarbon  
staining.

May 16, 2025 11:44:30 AM  
40.57359727565199N 106.38129995204508W  
Walden  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#20 Photo taken from north side of TB looking south. Note: holes in spray foam, It is believed that birds are attempting to tunnel into the spray foam insulation on the tanks and the insulation is becoming airborne and collecting in the containment.

May 16, 2025 11:44:42 AM  
40.573597443290055N 106.38135334476829W  
Walden  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



40.57358809746802N 106.3813986908644W  
May 16, 2025 11:44:53 AM  
Walden  
Colorado

Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#21 Photo taken from north side of TB looking south. Note: holes in spray foam, It is believed that birds are attempting to tunnel into the spray foam on the tanks and the insulation is becoming airborne and collecting in the containment.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#22 Photo taken  
from north side of TB  
looking south.

May 16, 2025 11:45:14 AM  
40.5736020533368N 106.38158443383873W  
Walden  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Pintail Tank  
Battery Spill  
Location ID: 454414  
Inspection Date: 05/16/2025

Photo#23 Photo taken  
from north side of TB  
looking south.

May 16, 2025 11:45:17 AM  
40.57359924539924N 106.38158736750484W  
Walden  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources