

Final Reclamation Inspection

May 9, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 329974

Inspection Document #: 718800295

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PSC #32-11
Location ID: 329974



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of seeding and straw mulch, but vegetation has not established to Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1. Photo illustrates that bare ground patches remain at the location.



Inspection Photos
Location Name: PSC #32-11
Location ID: 329974



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: PSC #32-11
Location ID: 329974



Photo 5. Photo taken of the reference area, east of the well site, facing Northeast. Photo illustrates perennial grass vegetation with evidence of disturbance from grazing.

