

# Final Reclamation Inspection

May 9, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 329894

Inspection Document #: 718800302

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: PSC #22-11  
Location ID: 329894



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that gravel remains on the location and vegetation on the site does not meet Rule 1004 requirements.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.





Inspection Photos  
Location Name: PSC #22-11  
Location ID: 329894



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.





Inspection Photos  
Location Name: PSC #22-11  
Location ID: 329894



**Photo 5.** Photo taken of the access road, facing West towards the location. Photo illustrates that the access road remains unreclaimed.



**Photo 6.** Photo taken of the well location. Photo illustrates that gravel remains at the location.





Inspection Photos  
Location Name: PSC #22-11  
Location ID: 329894



**Photo 7.** Photo taken of the reference area, west of the location, facing West.  
Photo illustrates perennial grass vegetation.

