

Inspection Photos
Location Name: Brown 31-33
API Number: 125-09147



1. Lease sign at well location.



2. View of wellhead. Note staining around Wellhead.

Inspection Photos
Location Name: Brown 31-33
API Number: 125-09147



3. Gas Meter inside Meter Box.



4. Well location overview.

Inspection Photos
Location Name: Brown 31-33
API Number: 125-09147



5. Open ended valve on water leg. Note stained soil around Wellhead.



4. Additional Well location overview.