

Inspection Photos  
Location Name: Brown 44-33R  
API Number: 125-07771



1. Lease sign at well location.



2. View of wellhead.

**Inspection Photos**  
**Location Name: Brown 44-33R**  
**API Number: 125-07771**



**3. Gas Meter inside Meter Box.**



**4. Well location overview.**