

Inspection Photos

May 13, 2025

Operator: Nuevida Resources - 10764

Location ID: 325319

Inspection Document #: 714002165

La Plata County, CO

Township: SWNW 4 33W 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

May 13, 2025
338° N



Photo 1. View of the project area taken from the southern edge facing center.

Inspection Photos
Location Name: Jacques 1
Location ID: 325319

May 13, 2025
342° N



May 13, 2025
75° E



Inspection Photos
Location Name: Jacques 1
Location ID: 325319

May 13, 2025
160° S



May 13, 2025
256° W





Photo 4. Field bindweed observed in various patches throughout the project area.

May 13, 2025
73° E

